county	ID	facilityName	populationServed	assessmentDate	vvlCurrentStatus	comments Second
Harris	1012806	ALTON THEISS SUBDIVISION	45	9/2/2017	<u> </u>	WTP not operational, significant damage.
				0/24/2047		#16 Follow up in 3-5 days #17 Entire system under potentially 4 feet of water. There isn't
Harris	1010085	APACHELAND MOBILE HOME SUBDIVISION	177	8/31/2017	INOP	access to the system.
Victoria	2350042	ARENOSA CREEK ESTATES	65	9/1/2017		residents evacuated and are returning; however, no power or water is available.
Liberty	1460025	BIG THICKET LAKE ESTATES 1	76	8/29/2017		
						#3 No power. Has only seen well site from a distance. Well house is gone. He plans to go
				0/24/2047		out today, 8/31/17, and evaluate the status. #5 Looking for a smaller more portable
				8/31/2017		generator to use. Plans to use it intermittently due to fuel concerns. #10 System is
Aransas	40058	CAPTAIN KENS RV PARK	30		INOP	completely down.
Jefferson	1230020	CARDINAL MEADS IMPROVEMENT	154	9/1/2017		
Orange	1810190	CHURCH OF JESUS CHRIST OF LDS VIDOR	681	9/1/2017	INOP	BWN will be posted at the church until negative TC/BacT samples come back.
						One GW Plant is down, it is underwater = snyder plant (TP1133)+ well (g0200001 B) Won't
				0/04/0047		be able to assess damage until utility water recedes Contact info for Brandon Moody,
l				8/31/2017		mobile 832 -398-0180 Backup contact: Brian Smith, Director of Public Services, 713-859-
Brazoria	200001	CITY OF ALVIN	24000		INOP	0482
l						2. Area under mandatory evacuation per system contact. Contact unable to get in to area
1						to view extent of damage. 3. Area under mandatory evacuation per system contact.
				9/1/2017	,	Contact unable to get int o area to view extent of damage. 7. Area under mandatory
						evacuation per system contact. Contact unable to get int o area to view extent of dama
1	4220040	CITY OF REVII OAKS	1274			11. Unable to montior quality of water. 12. No where to post notice, system under
Jefferson		CITY OF BEVIL OAKS	1274	0/27/2017	INOP	mandatory evacuation. Boil Water Notice materials sent to TCEQ BWN Dept.
Victoria	2350002	CITY OF VICTORIA	67444	8/27/2017		
A	40003	CORANO COVE CURRIVICIONI	1446	9/2/2017	INOR	facility averaging interestitant water continues to City of Backgrount for water average
Aransas	40003	COPANO COVE SUBDIVISION	1446			facility experiencing intermittent water. contingent on City of Rockport for water supply.
				8/31/2017		11. OPERATOR UNABLE TO ACCESS SITE DUE TO FLOODING. 12. BWN method of issuance
Harris	1011651	CYPRESS FIELDS SUBDIVISION	441			not specified.
l				8/31/2017		11. OPERATOR UNABLE TO ACCESS SITE DUE TO FLOODING. 12. BWN method of issuance
Harris		CYPRESS PLACE	147	0/00/0047	INOP	not specified.
		ENCHANTED FOREST	54	8/28/2017		11. Precautionary BWN issued. 12, BWN method of issuance not specified.
Brazoria	200218	HASTINGS HOMEOWNERS WATER SYSTEM	177	8/29/2017	INOP	BWN was issued due to power loss
						#2 Voluntarily shut down power to facility, no known damage. #4 Waiting on a generator
1						to be delivered. #5 Once the generator is in use, has more than a weeks worth of fuel
				8/31/2017		available on site. #7 The goal is to be, at least partially, operational tomorrow. Trying to
						have enough water for safety showers and sprinkler system, but not for drinking. #11
Liberty	1460085	HUNTSMAN PETROCHEMICAL DAYTON FACILITY			INIOD	
Liberty			50		INOP	Power outage.
LIDCITY	1460164	INDIAN SPRINGS WATER SYSTEM	50 183	8/28/2017		Power outage. Outage List
Liberty				8/28/2017		Outage List
LIDEITY				8/28/2017		Outage List 2, Unknown extent of damage at this time due to system experiencing flooding. 3.
Liberty					INOP	Outage List
Liberty				8/28/2017 9/2/2017	INOP	Outage List 2, Unknown extent of damage at this time due to system experiencing flooding. 3.
LIDEILY					INOP	Outage List 2, Unknown extent of damage at this time due to system experiencing flooding. 3. Unknown extent of damage at this time due to system experiencing flooding. 10. Intends
LINCILLY					INOP	Outage List 2, Unknown extent of damage at this time due to system experiencing flooding. 3. Unknown extent of damage at this time due to system experiencing flooding. 10. Intends to issue a boil water notice once able. 15. Customers are providing themselves with
					INOP	2, Unknown extent of damage at this time due to system experiencing flooding. 3. Unknown extent of damage at this time due to system experiencing flooding. 10. Intends to issue a boil water notice once able. 15. Customers are providing themselves with water. Contact is a volunteer operator for this system and needs technical assistance or
	1460164	INDIAN SPRINGS WATER SYSTEM	183		INOP	Outage List 2, Unknown extent of damage at this time due to system experiencing flooding. 3. Unknown extent of damage at this time due to system experiencing flooding. 10. Intends to issue a boil water notice once able. 15. Customers are providing themselves with water. Contact is a volunteer operator for this system and needs technical assistance or financial assistance for getting the system back up and running. Contact tates it could be
	1460164	INDIAN SPRINGS WATER SYSTEM	183	9/2/2017	INOP	Outage List 2, Unknown extent of damage at this time due to system experiencing flooding. 3. Unknown extent of damage at this time due to system experiencing flooding. 10. Intends to issue a boil water notice once able. 15. Customers are providing themselves with water. Contact is a volunteer operator for this system and needs technical assistance or financial assistance for getting the system back up and running. Contact tates it could be
	1460164	INDIAN SPRINGS WATER SYSTEM	183		INOP	Outage List 2, Unknown extent of damage at this time due to system experiencing flooding. 3. Unknown extent of damage at this time due to system experiencing flooding. 10. Intends to issue a boil water notice once able. 15. Customers are providing themselves with water. Contact is a volunteer operator for this system and needs technical assistance or financial assistance for getting the system back up and running. Contact tates it could be days or weeks until an assessment on system is possible. John Sexton self-reported an outage for the PWS on 8/28/2017 in the SB/LGA Outage
Harris	1011567	KINGSLAND ESTATES WSC	36	9/2/2017	INOP	2, Unknown extent of damage at this time due to system experiencing flooding. 3. Unknown extent of damage at this time due to system experiencing flooding. 10. Intends to issue a boil water notice once able. 15. Customers are providing themselves with water. Contact is a volunteer operator for this system and needs technical assistance or financial assistance for getting the system back up and running. Contact tates it could be days or weeks until an assessment on system is possible. John Sexton self-reported an outage for the PWS on 8/28/2017 in the SB/LGA Outage website. Q.3. Fallen trees tore out water lines. Q.7. Expect to have service restored on
Harris	1460164	INDIAN SPRINGS WATER SYSTEM	183	9/2/2017 8/29/2017	INOP	Outage List 2, Unknown extent of damage at this time due to system experiencing flooding. 3. Unknown extent of damage at this time due to system experiencing flooding. 10. Intends to issue a boil water notice once able. 15. Customers are providing themselves with water. Contact is a volunteer operator for this system and needs technical assistance or financial assistance for getting the system back up and running. Contact tates it could be days or weeks until an assessment on system is possible. John Sexton self-reported an outage for the PWS on 8/28/2017 in the SB/LGA Outage website. Q.3. Fallen trees tore out water lines. Q.7. Expect to have service restored on 8/30/2017. Q.16. Follow up on or after 8/31/2017 to check status.
Harris	1460164 1011567 1460007	KINGSLAND ESTATES WSC	36 435	9/2/2017 8/29/2017	INOP	Outage List 2, Unknown extent of damage at this time due to system experiencing flooding. 3. Unknown extent of damage at this time due to system experiencing flooding. 10. Intends to issue a boil water notice once able. 15. Customers are providing themselves with water. Contact is a volunteer operator for this system and needs technical assistance or financial assistance for getting the system back up and running. Contact tates it could be days or weeks until an assessment on system is possible. John Sexton self-reported an outage for the PWS on 8/28/2017 in the SB/LGA Outage website. Q.3. Fallen trees tore out water lines. Q.7. Expect to have service restored on 8/30/2017. Q.16. Follow up on or after 8/31/2017 to check status. 11. Precautionary BWN issued. 8/30 BWN Mandatory 12, BWN method of issuance not
Harris Liberty Harris	1460164 1011567 1460007 1011510	KINGSLAND ESTATES WSC LAKE LIVINGSTON BIG THICKET LAKE 2	36	9/2/2017 8/29/2017 8/28/2017	INOP INOP	Outage List 2, Unknown extent of damage at this time due to system experiencing flooding. 3. Unknown extent of damage at this time due to system experiencing flooding. 10. Intends to issue a boil water notice once able. 15. Customers are providing themselves with water. Contact is a volunteer operator for this system and needs technical assistance or financial assistance for getting the system back up and running. Contact tates it could be days or weeks until an assessment on system is possible. John Sexton self-reported an outage for the PWS on 8/28/2017 in the SB/LGA Outage website. Q.3. Fallen trees tore out water lines. Q.7. Expect to have service restored on 8/30/2017. Q.16. Follow up on or after 8/31/2017 to check status. 11. Precautionary BWN issued. 8/30 BWN Mandatory 12, BWN method of issuance not specified.
Harris Liberty Harris Matagorda	1460164 1011567 1460007 1011510 1610052	KINGSLAND ESTATES WSC LAKE LIVINGSTON BIG THICKET LAKE 2 MARKS GLEN SUBDIVISION MATAGORDA DUNES SUBDIVISION	183 36 435 258 426	9/2/2017 8/29/2017 8/28/2017 8/30/2017	INOP INOP INOP	Outage List 2, Unknown extent of damage at this time due to system experiencing flooding. 3. Unknown extent of damage at this time due to system experiencing flooding. 10. Intends to issue a boil water notice once able. 15. Customers are providing themselves with water. Contact is a volunteer operator for this system and needs technical assistance or financial assistance for getting the system back up and running. Contact tates it could be days or weeks until an assessment on system is possible. John Sexton self-reported an outage for the PWS on 8/28/2017 in the SB/LGA Outage website. Q.3. Fallen trees tore out water lines. Q.7. Expect to have service restored on 8/30/2017. Q.16. Follow up on or after 8/31/2017 to check status. 11. Precautionary BWN issued. 8/30 BWN Mandatory 12, BWN method of issuance not
Harris Liberty Harris	1460164 1011567 1460007 1011510	KINGSLAND ESTATES WSC LAKE LIVINGSTON BIG THICKET LAKE 2 MARKS GLEN SUBDIVISION	183 36 435 258	9/2/2017 8/29/2017 8/28/2017 8/30/2017 8/29/2017	INOP INOP INOP INOP	Outage List 2, Unknown extent of damage at this time due to system experiencing flooding. 3. Unknown extent of damage at this time due to system experiencing flooding. 10. Intends to issue a boil water notice once able. 15. Customers are providing themselves with water. Contact is a volunteer operator for this system and needs technical assistance or financial assistance for getting the system back up and running. Contact tates it could be days or weeks until an assessment on system is possible. John Sexton self-reported an outage for the PWS on 8/28/2017 in the SB/LGA Outage website. Q.3. Fallen trees tore out water lines. Q.7. Expect to have service restored on 8/30/2017. Q.16. Follow up on or after 8/31/2017 to check status. 11. Precautionary BWN issued. 8/30 BWN Mandatory 12, BWN method of issuance not specified. Outage List BWN issued due to well failure
Harris Liberty Harris Matagorda Montgomery	1460164 1011567 1460007 1011510 1610052 1700773	KINGSLAND ESTATES WSC LAKE LIVINGSTON BIG THICKET LAKE 2 MARKS GLEN SUBDIVISION MATAGORDA DUNES SUBDIVISION MONTGOMERY COUNTY MUD 119 SPRING TRAILS	183 36 435 258 426 3126	9/2/2017 8/29/2017 8/28/2017 8/30/2017 8/29/2017	INOP INOP INOP INOP	Outage List 2, Unknown extent of damage at this time due to system experiencing flooding. 3. Unknown extent of damage at this time due to system experiencing flooding. 10. Intends to issue a boil water notice once able. 15. Customers are providing themselves with water. Contact is a volunteer operator for this system and needs technical assistance or financial assistance for getting the system back up and running. Contact tates it could be days or weeks until an assessment on system is possible. John Sexton self-reported an outage for the PWS on 8/28/2017 in the SB/LGA Outage website. Q.3. Fallen trees tore out water lines. Q.7. Expect to have service restored on 8/30/2017. Q.16. Follow up on or after 8/31/2017 to check status. 11. Precautionary BWN issued. 8/30 BWN Mandatory 12, BWN method of issuance not specified. Outage List BWN issued due to well failure 11. OPERATOR UNABLE TO ACCESS SITE DUE TO FLOODING. 12. BWN method of issuance
Harris Liberty Harris Matagorda	1460164 1011567 1460007 1011510 1610052 1700773	KINGSLAND ESTATES WSC LAKE LIVINGSTON BIG THICKET LAKE 2 MARKS GLEN SUBDIVISION MATAGORDA DUNES SUBDIVISION	183 36 435 258 426	9/2/2017 8/29/2017 8/28/2017 8/30/2017 8/29/2017 8/31/2017	INOP INOP INOP INOP INOP	Outage List 2, Unknown extent of damage at this time due to system experiencing flooding. 3. Unknown extent of damage at this time due to system experiencing flooding. 10. Intends to issue a boil water notice once able. 15. Customers are providing themselves with water. Contact is a volunteer operator for this system and needs technical assistance or financial assistance for getting the system back up and running. Contact tates it could be days or weeks until an assessment on system is possible. John Sexton self-reported an outage for the PWS on 8/28/2017 in the SB/LGA Outage website. Q.3. Fallen trees tore out water lines. Q.7. Expect to have service restored on 8/30/2017. Q.16. Follow up on or after 8/31/2017 to check status. 11. Precautionary BWN issued. 8/30 BWN Mandatory 12, BWN method of issuance not specified. Outage List BWN issued due to well failure 11. OPERATOR UNABLE TO ACCESS SITE DUE TO FLOODING. 12. BWN method of issuance not specified.
Harris Liberty Harris Matagorda Montgomery	1460164 1011567 1460007 1011510 1610052 1700773	KINGSLAND ESTATES WSC LAKE LIVINGSTON BIG THICKET LAKE 2 MARKS GLEN SUBDIVISION MATAGORDA DUNES SUBDIVISION MONTGOMERY COUNTY MUD 119 SPRING TRAILS	183 36 435 258 426 3126	9/2/2017 8/29/2017 8/28/2017 8/30/2017 8/29/2017	INOP INOP INOP INOP INOP	Outage List 2, Unknown extent of damage at this time due to system experiencing flooding. 3. Unknown extent of damage at this time due to system experiencing flooding. 10. Intends to issue a boil water notice once able. 15. Customers are providing themselves with water. Contact is a volunteer operator for this system and needs technical assistance or financial assistance for getting the system back up and running. Contact tates it could be days or weeks until an assessment on system is possible. John Sexton self-reported an outage for the PWS on 8/28/2017 in the SB/LGA Outage website. Q.3. Fallen trees tore out water lines. Q.7. Expect to have service restored on 8/30/2017. Q.16. Follow up on or after 8/31/2017 to check status. 11. Precautionary BWN issued. 8/30 BWN Mandatory 12, BWN method of issuance not specified. Outage List BWN issued due to well failure 11. OPERATOR UNABLE TO ACCESS SITE DUE TO FLOODING. 12. BWN method of issuance

Waller	2370005	PATTISON WSC	1461	8/29/2017	INOR	Ms Chapa said the system is flooded and can not completely assess the level of damage. Will need follow up in one week to further assess the system's needs.
Calhoun	290028	PORT ALTO WSC	115	9/1/2017		will fleed follow up in one week to further assess the system's fleeds.
Harris	1010307	REDWOOD ESTATES MOBILE HOME PARK	510	8/28/2017		11. Precautionary BWN issued. 8/30 BWN Mandatory 12. BWN method of issuance not specified. 8/30/2017 - No Power Water and Wastwater
Montgomery	1700778	RIO VISTA SUBDIVISION	117	8/29/2017	INOP	Q.3. Well pump inoperative. Q.7. Will try to access and repair well on 8/30/2017. Access limited by flood waters. Q.16. Follow up on or after 9/1/2017 to check status.
Calhoun	290054	SEADRIFT COKE PLANT	180	8/30/2017	INOP	Generators used only to power a few offices. Facility is off-line and the main potable water line was damaged so no potable water can be distributed. The facility was informed that they needed to issue a boil water notice (BWN) prior to providing water to the facility. Once the distribution system has been adequately flushed and both pressure and disinfectant residual restored, bacteriological samples will need to be collected and once negative then BWN can be rescinded.
Harris	1010320	SHELL OIL DEER PARK	2585	8/29/2017	INOP	
Brazoria	200053	SNUG HARBOR SUBDIVISION	99	8/31/2017	INOP	
Aransas	40055	SUNSET BAY	0	9/1/2017	INOP	Power is expected to be restored by Setpember 8th. Nobody is living there now
Brazoria	200201	TDCJ RAMSEY AREA	5119	9/1/2017	INOP	2Q - TCDJ has evacuated these units associated with this PWS. System has been shut down since August 29. As of 9/1, they are waiting for water to recede to determine any damage before we turn system back on. 8-13Q - The TDCJ Ramsey Area serves 3 units and units ave been evacuated, they will have to check wells and water plant systems for any damage before they can make determination to turn system back on
Victoria	2350009	THE ESTATES OF SANDY HILLS	18	9/1/2017	INOP	The facility does not have power. The system only serves 11 customers. The customers are not residing in the area due to damage to trailers.
Calhoun	290003	UNION CARBIDE SEADRIFT PLANT	683	8/31/2017	INOP	Finishing electrical checkout. Generators are available but awaiting grid power which is expected to be restored by tomorrow (1/1/17). Once power is restored, water distribution will begin under BWN for toilets. Then system will be pressured up to flush and then BACT samples will be collected.
Brazoria	200019	WEYBRIDGE SUBDIVISION WATER SYSTEM	87	8/31/2017	INOP	

facilityName

ALTON THEISS SUBDIVISION

APACHELAND MOBILE HOME SUBDIVISION

ARENOSA CREEK ESTATES

BIG THICKET LAKE ESTATES 1

CAPTAIN KENS RV PARK

CARDINAL MEADS IMPROVEMENT

CHURCH OF JESUS CHRIST OF LDS VIDOR

CITY OF ALVIN

CITY OF BEVIL OAKS

CITY OF VICTORIA

COPANO COVE SUBDIVISION

CYPRESS FIELDS SUBDIVISION

CYPRESS PLACE

ENCHANTED FOREST

HASTINGS HOMEOWNERS WATER SYSTEM

HUNTSMAN PETROCHEMICAL DAYTON FACILITY

INDIAN SPRINGS WATER SYSTEM

KINGSLAND ESTATES WSC

LAKE LIVINGSTON BIG THICKET LAKE 2

MARKS GLEN SUBDIVISION

MATAGORDA DUNES SUBDIVISION

MONTGOMERY COUNTY MUD 119 SPRING TRAILS

NORTH WOODS ESTATES

NORTHWEST FOREST MUD

PALM CREST

PATTISON WSC

PORT ALTO WSC

REDWOOD ESTATES MOBILE HOME PARK

RIO VISTA SUBDIVISION

SEADRIFT COKE PLANT

SHELL OIL DEER PARK

SNUG HARBOR SUBDIVISION

SUNSET BAY

TDCJ RAMSEY AREA
THE ESTATES OF SANDY HILLS
UNION CARBIDE SEADRIFT PLANT
WEYBRIDGE SUBDIVISION WATER SYSTEM